


Fig 4-3, Beall Remediation Area.dwg - DWH - 04/13/2004 - S1176-11-FSEPRPT



- Legend**
- Monitoring Well Locations
 - Other Sampling Locations
 - Culvert
 - Fence
 - Property Boundary
 - Building
 - Concentration of Either PCE, TCE, CIS-1,2-DCE, or VC Exceeds MCL in Groundwater in April 2003
 - Estimated Extent of Contaminated Vadose Soil Above Remediation Goals



RECORD OF DECISION
LOCKWOOD SOLVENT GROUNDWATER PLUME SITE
BILLINGS, MONTANA

FIGURE 6
BEALL SOURCE AREA
SOIL REMEDIATION AREAS